
User Guide Evaluation Kit for TFT 4" MIPI interface no Touch

WWTFTDEMO40C-00#

TFT panel





Kit Assembling Guide

1) Connect the TFT display module to the PB1W0004R0*** (a) via FPC Cable
3) Insert 5V power adapter (b) to the WWPIC24F-A-00# (c) through power jack connector
4) Power ON through Power ON/OFF switch