



WINSTAR Display Co.,Ltd.

5F., No.31, Keya Rd., Daya Dist., Taichung City 428, Taiwan

TEL/+886-4-2568 9987 FAX/+886-4-2586 7763 E-mail/Sales@winstar.com.tw

Product Change Notification

■ Issue Date: October 19, 2022

■ Description: In order to improve production efficiency and yield, and more in line with the in-house process, the following metal frame and PCB optimization changes will be made.







■ Description of change:

1. Adding positioning column and the side seal opening on the metal frame .
2. The shape of the positioning holes of the metal frame on the PCB are changed from square to round, and the positions of some components are changed.

■ Effected model:

Effected Parts	WH4004A Series
----------------	----------------

■ Module Drawing Comparison

Before Change	After Change
	
The metal frame increases the positioning column and the side seal opening	
	
The positioning holes of the metal frame on the PCB are changed from square to round	
	
Changes in the position of some components on the PCB	